

01/12




FIG. 1A




FIG. 1B

09596657-061900

APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		

02/12

7

006190.2596560




FIG. 2

L

APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		

03/12

7

006190' 2996560




FIG. 3

APPROVED	O. G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		

04/12

006190-25996560




FIG. 4

05/12

7




FIG. 5A




FIG. 5B




FIG. 5C

09596657.061900

L

APPROVED	D.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		

06/12



FIG. 6A




FIG. 6B



FIG. 6C




FIG. 6D




FIG. 6E

006190-75996560

APPROVED	O.G. FIG.
BY	CLASS/SUBCLASS
DRAFTSMAN	

07/12

006190-25996560




FIG. 7

APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		

8/12

09596657-061900





FIG. 8

09/12

006F90-25996560

FIG. 9





10/12




FIG. 10

RECEIVED
 AUG 11 2003
 TECH CENTER

APPROVED	O.G. FIG.	
BY	CLASS	DECLASS
DRAFTSMAN		

11/12

006790 25996560




FIG. 11

APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		

006190-25936560

12/12

NTPBQR33-W13 "BUG" CHIPS, VARIOUS CONCENTRATIONS OF RCA5 BTR REPORTER IN 50 mM HISTIDINE, SPECIFIC/NON-SPECIFIC BINDING AFTER WASHING




FIG. 12